

New/Untaken Referrals November 2025

Referral	Problem	Location of job	Allocation
DB-25-043	Wheelchair Guards Modified side guards required for Invacare all-terrain wheelchair. The (side guards) are 11 inches long and have a very limited degree of adjustability. They are on a hinge and fold away when the backrest is folded down. The main issues are - they sit too low when I'm in the chair, which has led to some of my clothes being ruined, as mud, gravel etc gets on my trousers and the side guards are too small to prevent this. Some fender sideguards would be ideal, as these would prevent dirt and debris getting on my clothes	Derby DE3 0PL	
DB-25-051	Adapted Gloves Client had an injury in August 2025 which resulted in amputation of his right ring finger from his middle joint and little fingertip. He is an apprentice, and his job involves having to use welding gloves. He reports he struggles with these gloves as the ring finger gets in the way. Welding gloves need to be adapted for his hand.	Derby DE21 4GG	

DB-25-052	Toilet Solution Client is frequently falling asleep and then falling off his toilet. He was using a wheeled commode over the toilet but this has changed to a floor fixed toilet frame and raised toilet seat (as commode tipped onto him when he falls forward).He needs something that folds down in front of him that can be raised or lowered to either lean on or something in front that will prevent him tipping off toilet. He has sitting balance and is mobile over short distances with a Zimmer frame. He has good cognition.	Burton DE13 0DQ	
DB-25-053	Posture Support Patient struggles with core stability and trunk collapses to the right when sitting. Ideas needed on how to offer support to keep her sitting more centrally in her armchair. Pillows at the side of her have been tried but she takes them out.	Ambergate DE56 2JB	
DB-25-054	Bed Lever Client has difficulty moving on the bed to get in a good position up by the pillows. Standard bed levers do not fit the current bed or fit in the space between the bed frame and through floor lift. Bed is private profiling bed within a bed frame that sits on the floor.	Burton DE15 9NZ	
DB-25-055	Safety Gate(s) Three children either have or are being assessed for autism and ADHD. They do not have any danger/safety awareness and require constant supervision. Family have installed safety gates. However, the children are now able to climb over or break these off the walls. The family will benefit from robust gates to ensure the children are safe and cannot access areas of the home unsupervised	Derby DE22 2HW	

DB-25-056	Table Adaptation Client has self-purchased table. The table is not the right height for him to eat from and he is struggling when lifting his arm from table to mouth. Patient would like the table to be a little higher to enable him to feed himself. There is also a lip on the table that he is struggling to lift his arm over as he is feeding. Patient has a lot of positional aids in bed to support him and this impacts the height of the table.	Alvaston DE24 0HS	
DB-25-057	Laptop Solution Client has spine compression and 80% paralysed. He only has limited movement in his left arm and limited feelings in his left hand. He is fully compos mentis. He would like to use a laptop but movement is proving somewhat difficult; reach and touch.	Clay Cross S45 9DZ	